

Keunggulan Teknologi pembangkit vortex untuk mengatasi kerusakan bawang merah di gudang

Deskripsi Lengkap: <https://lib.ui.ac.id/detail?id=130138&lokasi=lokal>

Abstrak

Damage red onion in storage is caused by several factors including less than perfect initial drying, storage temperature and humidity in the barn is too high and air circulation is less smooth....