

Analisis sistem pencegahan penanggulangan dan tanggap darurat terhadap kebakaran di Perpustakaan Pusat Universitas Indonesia tahun 2012

Ratna Kusumaningsih, author

Deskripsi Lengkap: <https://lib.ui.ac.id/detail?id=20321145&lokasi=lokal>

Abstrak

Kebakaran merupakan suatu peristiwa atau kejadian yang dapat menyebabkan banyak kerugian. Penelitian ini bertujuan untuk melakukan analisis sistem pencegahan, penanggulangan dan tanggap darurat kebakaran di Perpustakaan Pusat Universitas Indonesia tahun 2012. Hasil dari penelitian ini selanjutnya akan dibandingkan dengan Kepmen PU No. 11/KPTS/2000, Kepmen PU No. 10/KPTS/2000, Permen PU No. 26/PRT/M/2008, Perda DKI Jakarta No. 8 Tahun 2008, dan standar Internasional NFPA 10, 13, 14, 72, dan 101. Klasifikasi bahaya gedung Perpustakaan Pusat Universitas Indonesia merupakan klasifikasi bahaya sedang I dan termasuk kebakaran kelas A dan C.

Hasil penelitian menunjukkan bahwa Perpustakaan Pusat Universitas Indonesia belum memiliki manajemen penanggulangan kebakaran yang sesuai dengan standar. Sistem proteksi aktif sudah cukup sesuai dengan standar. Struktur bangunan sudah memenuhi persyaratan. Sedangkan untuk pintu darurat dan tempat berkumpul sementara tidak diberi tanda. Gedung perpustakaan ini belum memiliki akses pemadam khusus serta program pemeriksaan dan pemeliharaan sarana kebakaran. Dari hasil penelitian diperoleh kesimpulan bahwa sistem pencegahan, penanggulangan dan tanggap darurat kebakaran di Perpustakaan ini masih perlu ditingkatkan, khususnya dalam hal manajemen.

<hr><i>Fire is an accident that can cause many losses. The objective of this study is to analyze fire prevention, protection, and emergency response in University of Indonesia's Central Library Building, Year 2012. The results of this study are then compared to Kepmen PU No. 11/KPTS/2000, Kepmen PU No. 10/KPTS/2000, Permen PU No. 26/PRT/M/2008, Perda DKI Jakarta No. 8 Tahun 2008, and NFPA 10, 13, 14, 72, 101. Building hazard classification for this library are classified as moderate I and class A and C.</i>

The results show that emergency response management doesn't exist and this is not comply to the regulation. Fire protection systems are quite appropriate with the regulation. Building structure has been complied to the regulation. Meanwhile, there are no sign for emergency doors and meeting point. This building didn't have fire fighter access and fire facility maintenance program. In conclusion, fire safety systems in this building need to be improved, especially for the emergency response management.</i>