

# Analisis Konsep Pembangunan Berorientasi Transit (TOD) di Stasiun KRL Depok Baru = Analysis of Transit-Oriented Development (TOD) Concept at Depok Baru KRL Station

Muhammad Ryandika, author

Deskripsi Lengkap: <https://lib.ui.ac.id/detail?id=20525906&lokasi=lokal>

---

## Abstrak

Populasi penduduk DKI Jakarta setiap tahunnya terus mengalami peningkatan sehingga mendorong terjadinya fenomena urban sprawl yaitu meluasnya kawasan perkotaan ke wilayah sekitar (Jabodetabek). Salah satu permasalahan yang timbul dari fenomena tersebut adalah kemacetan akibat masifnya penggunaan kendaraan pribadi. Untuk meningkatkan penggunaan angkutan umum massal, diperkenalkan sebuah konsep Transit Oriented Development (TOD) sebagai konsep pengembangan yang terpusat pada simpul transit salah satunya pada Stasiun KRL Depok Baru. Penelitian ini bertujuan untuk menilai dan menganalisis konsep TOD Stasiun Depok Baru sesuai dengan standar dan prinsip TOD. Instrumen penilaian yang digunakan untuk menganalisis adalah TOD Standard dari Institute for Transportation and Development Policy (ITDP) dan Indikator Kesiapan TOD (Iskandar et al., 2021). Dengan melakukan penilaian dan analisis, didapatkan hasil bahwa TOD Stasiun Depok Baru belum memenuhi semua aspek terdapat dalam TOD Standard dan Indikator Kesiapan TOD sehingga nilai yang didapatkan tidak maksimal. Perlu adanya perbaikan atau peningkatan pada beberapa aspek untuk mencapai fungsi TOD yang maksimal.

.....The population of DKI Jakarta continues to increase every year, causing the phenomenon of urban sprawl, or the expansion of urban areas into the surrounding area (Jabodetabek). One of the problems arising from this phenomenon is congestion due to the massive use of private vehicles. To increase the use of public transportation, a Transit-Oriented Development (TOD) concept was introduced as a development concept centered on transit nodes, one of which is located at the Depok Baru KRL Station. This study aims to assess and analyze the TOD concept at Depok Baru Station in accordance with TOD standards and principles. The assessment instrument used to analyze is the TOD Standard from the Institute for Transportation and Development Policy (ITDP) and the Readiness Indicators for Transit-Oriented Areas. An assessment and analysis found that the TOD of Depok Baru Station did not meet all the aspects contained in the TOD Standard and the TOD Readiness Indicator, so the value obtained was not optimal. There needs to be improvements in several aspects to achieve maximum TOD function.