

Karakteristik pola sebaran erosi di kampus Universitas Indonesia, Depok

Sinulingga, Roland, author

Deskripsi Lengkap: <https://lib.ui.ac.id/detail?id=20292882&lokasi=lokal>

Abstrak

Kampus Universitas Indonesia memiliki peranan yang sangat penting sebagai daerah penyangga bagi Kota Jakarta, Depok dan Sekitarnya. Salah satu permasalahan yang muncul adalah perubahan penggunaan tanah di kampus ini. Penelitian ini bertujuan untuk mengkaji mengenai karakteristik pola sebaran erosi di Kampus UI, Depok. Metode yang digunakan didalam penelitian ini adalahnMetode USLE. Beberapa variabel yang digunakan adalah curah hujan (R), karakteristik fisik tanah (K), panjang lereng (L), kemiringan lereng (S), jenis tanaman (C), dan tindakan konservasi (P). Hasil akhir penelitian menyatakan bahwa karakteristik erosi wilayah penelitian dipengaruhi oleh penggunaan tanah setempat. Sesuai klasifikasi menurut Bakosurtanal, terdiri atas empat buah klasifikasi yaitu erosi, sangat tinggi, tinggi, sedang, dan rendah. Pola sebaran erosi sangat tinggi terletak di unit lahan Berbukit Hutan Akasia dengan pola sebaran mengelompok. Untuk erosi dengan klasifikasi rendah mendominasi wilayah penelitian. Klasifikasi tersebut terletak di unit lahan Miring Landai Taman dengan pola sebaran mengelompok.

<hr><i>University of Indonesia campus has a very important role as a buffer area for the city of Jakarta, Depok and surrounding areas. One issue that arises is the change of land use on the campus. This research aims to examine the characteristics of the distribution pattern of erosion on the UI Campus, Depok. The methods used in this research is a USLE method. Some of the variables used are precipitation (R), the physical characteristics of the soil (K), the length of the slope (L), the slope (S), type of plant (C), and conservation measures (P). Final results of the study stated that the characteristics of soil erosion research areas affected by land use. According to the classification from Bakosurtanal, there's a four classifications for erosion, very high, high, medium, and low. The very high distribution pattern of erosion is located in the Hilly Forested Acacia land units with clumped distribution pattern. The low erosion type area dominates in the research area which is located in the land units of Park Sloping Ramps with clumped distribution pattern.</i>