

# **Kelongsoran pada Bantaran Sungai Studi Kasus Bantaran Kali Ciliwung Wilayah Jakarta Selatan dan Timur**

Deskripsi Lengkap: <https://lib.ui.ac.id/detail?id=20304656&lokasi=lokal>

---

## **Abstrak**

Slope failure at river bank often occur in the rainy season. A study of characteristics of the location is needed in order to find the right way to prevent it. This study will calculate the safety factor value, which will vary depends on the surroundings factor. By the end of the study, we will get the most influencing factor that trigger the failure.