

Analisa Petrofisika dan Evaluasi Reservoir Pada Lapangan Barent Sea. = Analysis of Petrophysic and formation Evaluation for Reservoir of Rock on Barent Sea Field

Riyan, author

Deskripsi Lengkap: <https://lib.ui.ac.id/detail?id=20308518&lokasi=lokal>

Abstrak

Pada studi ini telah dilakukan analisis petrofisika dan evaluasi reservoir pada lapangan Barent Sea. Analisis petrofisika dan evaluasi formasi dilakukan pada enam buah sumur yaitu C1, C2, C3, C4, C5 dan C6, yang tersebar pada lapangan Barent Sea. Identifikasi reservoir dihasilkan dari parameter sifat fisik suatu batuan seperti porositas, kandungan lempung, permeabilitas, dan saturasi air yang dihasilkan dari perhitungan evaluasi formasi. Evaluasi formasi yang dilakukan meliputi tahapan identifikasi zona target, perhitungan kandungan lempung, porositas, saturasi air dan hasilnya ditampilkan dalam lumping. Dari studi ini dihasilkan parameter petrofisika untuk mempresentasikan batuan reservoir pada setiap zona-zona potensial. Dari enam buah sumur dan lima diantaranya memiliki rata rata nilai porositas yaitu 15%, kandungan lempung 7% dan saturasi air 44%, sedangkan satu buah sumur tidak memiliki zona yang potensial karena memiliki nilai saturasi air yang tinggi yaitu diatas 84%.

.....In this study has analysed of petrophysic and reservoir evaluation on Barent Sea field. The analys of petrophysic and formation evaluation carried on six of wells; are C1, C2, C3, C4, C5 and C6 on Barent Sea's field spreadly. The result of identification resevoar from behavior physic parameter of rocks are porosity, concentrate of clay, permeability and water saturation that calculated from formation evaluation. On this formation evaluation consist of identification of target zone level, concentrate of clay measurement, porosity, water saturation, and the result will be displayed on lumping. Petrophysic parameter resulted from this study for presentating of reservoir rocks on each of potential zone. From these six of wells and five of wells found porosity average is 15%, concetrates of clay is 7% and water saturation is 44%, whereas one of well is not contained of potential zone since the water saturation is high above 84%.