

# Mitigasi bencana Tsunami pada kawasan Kecamatan Meuraxa = Tsunami disaster mitigation in Sub Meuraxa

Nirmala Hayati, author

Deskripsi Lengkap: <https://lib.ui.ac.id/detail?id=20331884&lokasi=lokal>

---

## Abstrak

Kejadian tsunami 26 Desember 2004 di Aceh telah menimbulkan banyak dampak kerugian, terutama korban jiwa. Di kecamatan Meuraxa korban jiwa mencapai 92,725% dari jumlah penduduknya. Dampak yang sangat besar ini sangat berpengaruh terhadap pengembangan kawasan di daerah tersebut dan sangat diperlukan upaya mitigasi bencana untuk dapat mencegah dampak yang lebih besar terjadi lagi. sehingga masalah bencana tsunami menjadi perhatian yang serius bagi pemerintah untuk ditindaklanjuti dan dicari solusinya. Adanya kejadian tsunami ini mengubah pandangan pemerintah dalam penanggulangan bencana dari reaktif menjadi preventif. Sehingga beberapa daerah yang rentan bencana salah satunya di Kecamatan Meuraxa telah membuat beberapa fasilitas sebagai upaya mitigasi bencana tsunami. Beberapa diantaranya sangat erat kaitannya dengan rencana tata ruang kawasan tersebut, seperti peta arah evakuasi, rambu penunjuk arah evakuasi, jalur evakuasi, escape building, vegetasi hutan bakau dan sirine peringatan dini tsunami. Namun, pada kenyataannya fasilitas ini masih belum dapat terkoordinasi dengan baik dan tidak sinergis, sehingga sistem mitigasi bencana tsunami yang dihadirkan tidak berjalan dengan semestinya.

.....December 26, 2004 tsunami in Aceh has caused a lot of the impact of losses, especially fatalities. In sub Meuraxa victims reached 92.725% of the total population. Enormous impact is very influential on the development of the area and mitigation is necessary to prevent a greater impact happened again. so the problem of the tsunami disaster a serious concern for the government to follow up and find a solution. The existence of the tsunami is changing the views of government in disaster management from reactive to preventive. So some disaster-prone areas in the district one Meuraxa has made some facilities as the tsunami disaster mitigation. Some of them are closely related to the spatial plans, such as evacuation maps direction, directional signs for evacuation, evacuation routes, escape building, mangrove vegetation and tsunami early warning sirens. However, in reality these facilities still can not well coordinated and not synergistic, so the tsunami disaster mitigation systems that are not running properly presented.